



Laser Match Notes

Applies only to Fusion Maker, Fusion Edge, and Fusion Pro systems with Firmware 1.0.6.0 and higher.

After updating to 1.0.6.X, laser match may need to be recalibrated if it was adjusted from factory settings at a DPI other than 500.

In 1.0.6.X, an issue was fixed with how the firmware handles laser match at it now scales with the job DPI. When updating to 1.0.6.X, the laser match value will be modified to be correct now that the firmware handles it correctly.

1. If laser match hasn't been modified from factory settings, there is nothing that needs to be done. The new firmware will adjust the laser match value appropriately, and now laser match will scale with the job DPI.
2. If laser match has been modified from factory settings to work better at a DPI other than 500, you may notice laser match issues after updating to 1.0.6.0. To fix it, perform the steps to configure laser match. Now laser match will scale with the job DPI.