Fusion Series Suggested Material Settings (CO2)

E .:. 0. :	•			0 - 111	- /000	<u> </u>	
Fusion Series	Sugges		ateriai a	Setting	s (GUZ)	
Material	DPI/Freq.	30 watt	40 watt	50 watt	60 watt	75 watt	120 watt
Acrylic							
Photo Engraving	300 dpi	90s 50p	90s 45p	90s 40p	90s 35p	90s 30p	90s 20p
Text/Clipart Engraving	300 dpi	90s 75p	90s 70p	90s 65p	90s 60p	90s 55p	90s 45p
Text/Clipart Engraving	600 dpi	90s 55p	90s 50p	90s 45p	90s 40p	90s 35p	90s 25p
Cutting 1/8" (3 mm)	100 f	7s 100p	9s 100p	10s 100p	12s 100p	15s 100p	15s 100p
Cutting 1/4" (6 mm)	100 f	2s 100p	3s 100p	4s 100p	5s 100p	6s 100p	7s 100p
Cutting 3/8" (9.5 mm)	100 f	-	-	-	2s 100p	4s 100p	5s 100p
Cutting 1/2" (13 mm)	100 f	-	-	-	-	-	2s 100p
Cutting Note: Adjusting the sta 1/4" acrylic and thicker. Two p cast is better for engraving (c	asses may produc	ce better results a	and allow for cutt	ing through thick	er materials. The	ere are two type	
Alumamark	I	l	00 45	l	l	l aa aa	l
Engraving -	300 dpi	90s 55p	90s 45p	90s 35p	90s 25p	90s 20p	90s 15p
Engraving	600 dpi	90s 45p	90s 35p	90s 25p	90s 15p	90s 10p	90s 5p
Anodized Aluminum	I 000 1 :	l oo 40	00.05	I aa aa	I 00 05	I 00 00	l 00 45
Photos/Clipart	300 dpi	90s 40p	90s 35p	90s 30p	90s 25p	90s 20p	90s 15p
Photos/Clipart	600 dpi	90s 35p	90s 30p	90s 25p	90s 20p	90s 15p	90s 10p
Text	600 dpi	90s 40p	90s 35p	90s 30p	90s 25p	90s 20p	90s 15p
We find when engraving anod 300 dpi.	We find when engraving anodized aluminum, text appears best at 600 dpi, but photos and clipart can be engraved with great detail down to 300 dpi.						
Cork			·				
Engraving	300 dpi	90s 50p	90s 45p	90s 40p	90s 30p	100s 35p	100s 25p
Fleece							
Engraving	300 dpi	90s 35p	90s 30p	90s 25p	90s 20p	90s 15p	90s 10p
When engraving fabric, try chawill need to have adjusted sett					for the best resul	lts. Every fabric	you are cutting
Glass							
Engraving	300 dpi	15s 100p	25s 100p	30s 100p	40s 100p	75s 100p	100s 100p
When etching glass, try chang covering the glass with a thin			e engraving and ι	ising the Jarvis d	ithering pattern.	You can also di	ffuse heat by
Leather							
Photo Engraving	300 dpi	90s 40p	90s 45p	90s 50p	90s 55p	90s 60p	90s 65p
Text/Clipart Engraving	600 dpi	90s 50p	90s 55p	90s 60p	90s 65p	90s 70p	90s 75p
Cutting 1/8" (3 mm)	50 f	30s 90p	40s 90p	50s 90p	60s 90p	70s 90p	80s 100p
Mat Board							
Cutting	50 f	20s 50p	20s 45p	20s 40p	20s 35p	20s 30p	20s 25p
Marble							
Photo Engraving	300 dpi	90s 55p	90s 50p	90s 45p	90s 40p	90s 35p	90s 254
Text Engraving	600 dpi	90s 60p	90s 55p	90s 50p	90s 45p	90s 40p	90s 30p
Every marble is very different	for settings. Start	low and increase	the power with a	a second run if yo	ou haven't used t	that marble befo	re.

Fusion Series Suggested Material Settings (CO2)

Fusion Series							
Material	DPI/Freq.	30 watt	40 watt	50 watt	60 watt	75 watt	120 watt
Painted Brass		1	<u>, </u>	ï		,	1
Engraving	300 dpi	90s 45p	90s 40p	90s 35p	90s 30p	90s 25p	90s 15p
Engraving	600 dpi	90s 40p	90s 35p	90s 30p	90s 25p	90s 15p	90s 10p
Plastics							
Engraving	300 dpi	90s 40p	90s 35p	90s 30p	90s 25p	90s 20p	90s 15p
These settings work well with engraved.	n many plastics, i	ncluding plastic p	hones and cover	s. Even one colo	r plastics can ach	ieve a great loo	k when
Plastic (2 Layer Engraveable)						
Engraving	300 dpi	90s 80p	90s 75p	90s 70p	90s 65p	90s 60p	90s 55p
Engraving	600 dpi	90s 70p	90s 65p	90s 60p	90s 55p	90s 50p	90s 40p
Cutting 1/8" (3 mm)	100 f	15s 100p	20s 100p	30s 100p	30s 85p	30s 70p	30s 40p
Rubber Stamps							
Engraving	400 dpi	6s 100p	10s 100p	20s 100p	30s 100p	50s 100p	70s 100p
Engraving	600 dpi	16s 100p	20s 100p	30s 100p	40s 100p	60s 100p	80s 100p
Cutting	100 f	10s 100p	15s 100p	20s 100p	25s 100p	40s 100p	50s 100p
Stainless Steel w/Cermark							
Engraving	600 dpi	20s 100p	25s 100p	30s 100p	35s 100p	45s 100p	55s 100p
Twill							,
Cutting	25 f	50s 40p	50s 40p	70s 100p	100s 100p	100s 80p	100s 60p
Wood							
Photo Engraving	600 dpi	40s 100p	45s 100p	50s 100p	55s 100p	60s 100p	75s 100p
Clipart/Text Engraving	600 dpi	30s 100p	35s 100p	40s 100p	45s 100p	50s 100p	60s 100p
Clipart/Text Engraving	300 dpi	25s 100p	30s 100p	35s 100p	40s 100p	45s 100p	55s 100p
Deep Engraving	600 dpi	10s 100p	15s 100p	20s 100p	25s 100p	30s 100p	35s 100p
Thin Veneer	20 f	30s 22p	30s 18p	30s 14p	30s 12p	30s 9p	30s 6p
Cutting 1/8" (3 mm)	20 f	12s 100p	15s 100p	20s 100p	30s 60p	20s 100p	40s 100p
Cutting 1/4" (6 mm)	20 f	6s 100p	8s 100p	10s 100p	15s 100p	10s 100p	20s 100p
Cutting 3/8" (9.5 mm)	20 f	-	-	5s 100p	8s 100p	6s 100p	12s 100p
Cutting 1/2" (12 mm)	20 f	-	_	-	_	-	6s 100p

- These are only suggestions: Every type of material will react differently with the laser, even from one plastic to the next. But don't feel that you need to be exact on any of the settings. While engraving acrylic at 35% speed and 75% speed will give you a very different result, the difference between 35% and 39% will be much more subtle and relies more on personal preferences.
- **Test your material:** If you have a small area of the material you won't be using, or an extra of the item, take advantage of this area to test out your settings by engraving a small square or cutting a small circle. You can fine tune your settings in these areas.
- Similar materials use similar settings: When you are working with a material you aren't familiar with, think about a similar material and what settings you would use with that product. Most anodized aluminums will react well with similar settings, as will most plastics.

Fusion Series Suggested Material Settings (Fiber)

- When in doubt, start low: Remember, you can always re-run your job as long as you don't move it in the machine. Let's say you're running a photograph in a one-of-a-kind wood plaque. Start with a lower power setting, look at the engraving, then run the project a second time at high speed and lower power a second time to add a little more depth if needed.
- Run only one part of the file: If running a job on a new material, you can always just select one piece of the engraving, like a piece of text, and run that part first to make sure your settings are perfect before running the whole file.



To print a copy of these settings to keep next to your laser, go to www.epiloglaser.com/material-settings.htm.

Fusion Series Suggested Material Settings (Fiber)								
Material	DPI/Freq.	20 watt	30 watt	50 watt				
Aluminum (Anodized)								
Etching/Marking	600 dpi	Speed: 20-50% Power: 70-100% Frequency: 50-100% Focus:03 to +.03	Speed: 40-70% Power: 50-100% Frequency: 50-100% Focus:03 to +.03	Speed: 40-80% Power: 50-100% Frequency: 50-100% Focus:03 to +.03				
The contrast / brightness of marks achievable on the fiber laser are excellent and are often much brighter than those done on a CO2 laser. The key is to broaden the beam by changing the focal setting by .03 to .05". This prevents the beam from ablating the anodized coating and penetrating the metal (results in dull white/gray marks). Lower frequency and higher power settings help offset the change in focal point. Different grades of anodized & core aluminum alloy will affect how the final marks look. Finding the right printing parameters is key in achieving a highly contrasting mark.								
Aluminum (Bare)								
Etching/Marking	600 dpi	Speed: 5-25% Power: 100% Frequency: 1-20% Focus:01 to +.01	Speed: 5-35% Power: 100% Frequency: 1-20% Focus:01 to +.01	Speed: 5-50% Power: 100% Frequency: 1-20% Focus:01 to +.01				
coat, clear anodized). Deep	o metal engraving on alu	s for a black etch, consider using an minum can be done in just a few pas they are on steel, we have no difficu	ses, consider deep engraving and	using a black epoxy/color fill.				
Etching/Marking	600 dpi	Speed: 5-30% Power: 100% Frequency: 1-20% Focus: 0	Speed: 10-60% Power: 100% Frequency: 1-5% Focus: 0	Speed: 15-60% Power: 100% Frequency: 1-10% Focus: 0				
Laserable Plastic								
Etching/Marking	600 dpi	Speed: 40-70% Power: 50-70% Frequency: 50-100% Focus:02 to +.02	Speed: 40-100% Power: 50-100% Frequency: 50-100% Focus:02 to +.02	Speed: 50-100% Power: 40-80% Frequency: 50-100% Focus:02 to +.02				
Stainless Steel								
Annealing	600 dpi	Speed: 5-10% Power: 100% Frequency: 1-5% Focus:08 to1 +.05 to +.08	Speed: 7-12% Power: 100% Frequency: 1-5% Focus:08 to1 +.05 to +.08	Speed: 12-17% Power: 100% Frequency: 1-10% Focus:08 to1 +.05 to +.08				
Etching/Marking	600 dpi	Speed: 10-30% Power: 100% Frequency: 1-35% Focus:01 to +.01	Speed: 10-50% Power: 100% Frequency: 1-20% Focus:01 to +.01	Speed: 15-60% Power: 100% Frequency: 1-20% Focus:01 to +.01				

Fusion Series Suggested Material Settings (Fiber)

Fusion Series Suggested Material Settings (Fiber)

Material	DPI/Freq.	20 watt	30 watt	50 watt
Polishing	600 dpi	Speed: 50-80% Power: 30-50% Frequency: 70-100% Focus: 0	Speed: 50-80% Power: 30-50% Frequency: 70-100% Focus: 0	Speed: 50-80% Power: 30-50% Frequency: 70-100% Focus: 0

Etching: Like our CO2 counterparts, the slower the speed setting, the deeper the etching. However, many metal applications can be processed at higher speed settings in the range of 50-100%. Again, consider the marking requirements. If the only stipulation is permanency, you'll find the FiberMark can engrave a broad range of metals at higher speeds, regardless of laser wattage. Don't be afraid to turn up the juice!

Annealing: To achieve an annealed mark, the focal point should be significantly away from zero. The unfocused, broader beam provides the heat to change the surface color without actually penetrating the metal. The focal point can be either closer to or away from zero. Focusing away from the material should be in the range of -.060" to- .090". Focusing closer to the material is generally in the range of +.070" to +.110".

Both focusing methods will result in a dark black annealing of the metal. Focusing up typically results in a slight indentation of the metal. Multiple passes can darken the mark even more (no data to confirm whether multiple passes offer more permanency).

Polishing: Some steel alloys are easier to polish than others. For best results, clean off the surface with alcohol prior to processing. Any leftover grease, oils or residue can affect how well the polished mark turns out. Polishing the metal where the final marks result in a bright white engraving requires finer tuning of settings, more so than the etched or annealed marks. Determine a base speed and frequency setting and adjust the power in small increments/ decrements. If you are unable to get a white bright mark, increase the frequency setting and try again by adjusting only the power.

Titanium					
Annealing	600 dpi	Speed: 5-10% Power: 100% Frequency: 1-5% Focus:08 to1 +.05 to +.08	Speed: 7-12% Power: 100% Frequency: 1-100% Focus:08 to1 +.05 to +.08	Speed: 12-17% Power: 100% Frequency: 1-100% Focus:08 to1 +.05 to +.08	
Etching/Marking	600 dpi	Speed: 10-20% Power: 100% Frequency: 1-10% Focus:02 to +.02"	Speed: 10-40% Power: 100% Frequency: 1-10% Focus:02 to +.02"	Speed: 15-60% Power: 100% Frequency: 1-15% Focus:02 to +.02"	

Titanium and Ti alloys are highly amenable to marking at this wavelength. Similar to aluminum, a black mark from the etching process is difficult to achieve. Various shades of gray can be made, from very dark gray to light gray. Annealed marks can also be made on titanium materials using the same processing parameter described for stainless steel. Depending on the Ti alloy, marks of various colors can be achieved by changing the frequency values for 1% up to 100%. It is common to see red, blue, green, orange, yellows and purple marks, depending on the frequency selected.

Plated Metals							
Etching/Marking	600 - 1200 dpi	Speed: 10-20% Power: 100% Frequency: 1-10% Focus:03 to05" +.03 to .05"	Speed: 10-20% Power: 100% Frequency: 1-10% Focus:03 to05" +.03 to .05"	Speed: 10-20% Power: 100% Frequency: 1-10% Focus:03 to05" +.03 to .05"			

Metals are often plated to assist with conductivity, to provide a protective coating against rust and elements and for aesthetic purposes. Plating thickness will depend on application and purpose. Most of the plated metals processed through the applications lab are electronic components (to enhance conductivity) and various fittings (protection against environment & rust). The typical plating thickness varies from .001" up to .005".

Our recommended settings for general metal engraving works well for ablating through the plating; exposing the base metal. Ablating the plating will also provide high contrast. Using an oxidizer will enhance the look.

Our recommended settings for polishing of metals are a good starting point where ablating through the plating isn't an option. This is likely the most common plated metal application as exposing the raw metal underneath will break continuity and / or expose the bare metal to rust and other elements. Note that the contrast of polishing of plated metals won't be as consistent or contrasting as a direct ablation. Multiple passes will help and end results will vary based on the metal used for plating, thickness of plating & size of mark.

Our recommended settings for annealing will often work for plated metals where the plating has a thicker wall and material used has high levels of carbon or metal oxides.

Fusion Series Suggested Material Settings (Fiber)

Fusion Series Suggested Material Settings (Fiber)						
Material	DPI/Freq.	20 watt	30 watt	50 watt		
Powder Coating						
Etching/Marking	600 dpi	Speed: 10-20% Power: 100% Frequency: 1-10% Focus:03 to05" +.03 to .05"	Speed: 10-20% Power: 100% Frequency: 1-10% Focus:03 to05" +.03 to .05"	Speed: 10-20% Power: 100% Frequency: 1-10% Focus:03 to05" +.03 to .05"		

Two to three passes are suggested (one pass to ablate the powder coating, 2nd or 3rd pass to polish up the metal underneath). A little less power, higher frequency and less focus adjustment will be required for the 2nd or 3rd pass, depending on the base metal. The idea is to ablate then polish. An alternative to running two or more passes is to run one pass and then use a common cleaner such as Simple Green or a citric-based cleaner with short, stiff bristle brush to scrub out the residual material remaining in the mark area. If using this technique, it may be necessary to raise or lower the marking table from around 0.07" to 0.10".

- These are only guidelines: Brightness or darkness of a mark is a matter of personal preference and can be very dependent of the type of material being marked. As such, there is no "correct" setting. Working with the four different settings becomes fairly intuitive in a very short period of time for most users. If you have a material that is not listed, try to compare it to similar materials listed and use those settings as your starting point.
- **Speed Settings:** The speed setting scale of 1% to 100% is not linear i.e. 100% speed will not be twice as fast as 50% speed. This non-linear scale is very useful in compensating for the different factors that affect engraving time.
- Power Settings: The power settings are linear i.e. 50% power is half as much as 100% power.
- General Metal Engraving / Base Settings: In the world of metals the grade, type, hardness and chemical composition are endless. Metal alloys are engineered for specific applications and have their own strengths and weaknesses. With such an unlimited selection, we've yet to come across a metal which proved to be incompatible with the FiberMark. Metals can be engraved at just about any settings. Of course, there are many variables to consider for metal engraving. The lasers wattage, hardness of metal, desired mark (etch, polish, anneal) and the required time/contrast/depth will have to be considered when deciding on the final settings.
- **General Annealing Settings:** Producing an annealed mark is very dependent on the material being out of focus. Run the laser at slow speed and full power then adjust the focus while the machine is running until you achieve the annealed mark you need.
- **Test your material:** If you do not achieve the results you are looking for with the recommended settings, try resending the job and start by changing only one variable at a time. Changing only one variable at a time will help to determine the correct setting for your material.
- Laser settings can sometimes be confusing because many materials can be marked over such a broad range of settings. If you have
 difficulty in finding the correct setting you can send a sample to the Epilog Laser Applications lab. We will determine if the material can
 be marked and provide appropriate setting for your laser.



To print a copy of these settings to keep next to your laser, go to www.epiloglaser.com/material-settings.